

## DEPARTMENT OF PUBLIC HEALTH AND PREVENTIVE MEDICINE REGIONAL PUBLIC HEALTH WATER ANALYSIS LABORATORY, TIRUNELVELL-11

From
Thiru.D.Asir Selvaraj B.Sc., B.Ed.,
Chief Water Analyst,
Regional Public Health Water
Analysis Laboratory,
Tirunelveli - 627 011.

To
The Correspondent,
GVJ International school,
S.No.6, Uppathur Vilakku,
N.Venkateshwarapuram, Sattur Taluk,
Virudhunagar district-626 205.

## R.No: 420/L/2023/M.026/CWA/Tvl., Dated: 20.07.2023

Sir / Madam,

Sub: Report on Examination of water sample from GVJ International School, S.No.6, Uppathur Vilakku, N.Venkateshwarapuram, Sattur Taluk, Virudhunagar District collected on 17.07.2023.

\*\*\*\*\*\*

A sample of water stated to have been collected on 17.07.2023 from R.O unit outlet near 3<sup>rd</sup> standard class room at GVJ international school, S.No.6, Uppathur Vilakku, N.Venkateshwarapuram, Sattur Taluk, Virudhunagar District (Source: Bore well) by Thiru. R.Ramesh Kannan, Correspondent was received at this laboratory on the same day from the addressee to assess its suitability for drinking purpose.

The results of analysis are furnished overleaf.

The sample of water is colorless and clear in physical appearance.

Judged by the results of analysis it is of satisfactory chemical and bacteriological quality for drinking.

Chief Water Analyst, Regional Public Health Water Analysis Laboratory, Tirunelveli-11.

Copy to: Lab & File.

GVJ INTERNATIONAL SCHOOL
N. Venkateshwarapuram-626 205

Sattur Taluk

Correspondent

GVJ INTERNATIONAL SCHOOL
N. Venkateshwarapuram-626 205

Sattur Taluk

## SCHOOL SANITARY CERTIFICATE

APPENDIX - 3

(Chapter III Rule - 24) Tamil Nadu Educational Rules

I, hereby declare that I have inspected the School

## GVJ INTERNATIONAL SCHOOL (CBSE), N. VENGATESHWARAPURAM, UPPATHUR VILAKKU, SATTUR TALUK, VIRUDHUNAGAR DISTRICT.

School Building and premises on the day

20.03.2023 and certify

- That the accommodation provided for each of the several classes is sufficient. For the minimum number of pupils taught therein and is properly ventilated and lighted
- That the building is maintained in substantial repair. That is neat and clean
- That the latrine arrangements are adequate and satisfactory
- That in all other necessary respects the sanitation is good.
- Drinking water source should be chlorinated daily.
- The water tanks (sintex/cement tanks) in the school campus should be kept clean by protecting it from mosquitoes.
- In school campus the wastages like plastic items, broken bottles and unused tyres should be replaced immediately from the rain water.
- In school campus check every item whether the rain water staged in the terrace.
- Adequate fire precautionary measures should be provided.
- Adequate Emergency Exit should be provided.
- In School campus display of sign boards of size 60 cm x 30 cm (No smoking area smoking here is an offense) inside the institution.
- In School campus no sale of tobacco in the radius of with 100 yards in the educational institutions.
- Hand Sanitizers should be available in each classroom.
- The entire pupils in the school should be screened by IR Thermal scanner daily.
- Hand washing facilities should be made in front of each and every buildings in the school.
- Social distancing (atleast 6 feet) should be maintained at all places in the campus.
- The school should follow the SOP's updated by the Government then and there.

This certificate is valid for one year from the date of issue.

(COO) GOVT.PRIMARY HEALTH CENTRE UPPATHUR

L.DIS. No. 1394/A3/SC/2023 dated: 21. 3.2023

Technical PA to QDHS

COUNTERSIGNED

To.

The Correspondent,

GVJ INTERNATIONAL SCHOOL (CBSE), N. VENGATESHWARAPURAM, UPPATHUR SATTUR TALUK, VIRUBHUNAGAR DISTRICT-626205.

Principa GVJ INTERNATIONAL SCHOOL N. Venkateshwarapuram-626 205

Sattur Taluk

espondent

GVJ INTERNATIONAL SCHOOL N. Venkateshwarapuram-626 205

Sattur Taluk